Hen Island Violation List - Revised March, 2009

North End

- No potable water (all cottages)
- Sewage privies under homes and along shore in some cases no approvals (all cottages)
- 12 volt and 110 electrical systems (most cottages)
- Propane lines and improper storage (all cottages)
- Water troughs (mosquito breeding sites) (all cottages)
- · No backboards or other life saving devises for beach or docks
- No fire extinguishers or ring buoys all docks
- · Wood stored rear of North Island
- Sewage privy (close to high tide water line) cottage # 3
- Sewage privies (block wall above ground privies) cottage # 1
- Steel buried in beach for erosion control cottage # 1
- No domestic water, privy clogged, cottage abandon, cottage # 2
- Filling in the buffer zone between cottage # 4 and cottage # 3
- Severe mosquito infestation
- Dock damaged attractive nuisance cottage # 7
- Steel stairs leading to beach rotted without rail cottage # 8
- New wall and walkway constructed without permits cottage # 9
- New electrical system and propane piping installation without permits cottage # 9
- Exposed privy, rotted wooden top, emitting odors, cottage # 11
- Rodent infestation cottage # 11
- Rodent infestation cottage # 12

Middle Section

- No potable water (all cottages)
- Sewage privies under homes in water table less than two feet (all cottages)
- 12 volt and 110 electrical systems (all cottages)
- Water troughs (mosquito breeding sites) (all cottages)
- Sewage privy (close to high tide water line) cottage # 20
- Propane lines and improper storage (all cottages)
- Cottage #19 rebuilt in 1993 (no privy approval from WCDOH as per wetlands permit, no electrical or plumbing inspections since rebuilding)
- Severe mosquito infestation especially in path to North Island
- No fire extinguishers or ring buoys for dock
- No backboards or other life saving devises for beach
- Abandon over twelve years, open privy, cottage # 18
- Soil retention wall built below water line on beach no permit cottage # 19 & 20
- Exposed electrical wires outside cottage #20
- · Wood, tires and debris on beach and shoreline

South End

- No potable water (all cottages)
- Sewage privies under homes (most cottages)
- Garbage can in ground used for sewage pit Ederer cottage
- 12 volt and 110 electrical systems (some cottages) propane lines and improper storage (most Cottages)
- Major fire 2006 cottage # 23
- Water troughs (mosquito breeding sites) (all cottages)
- · Steel walkway and tires buried on beach

- Buried oil tank on shoreline
- New cottage constructed without health approvals (sewer and domestic water)
- Cottage # 27 wood and debris on beach and shoreline
- *No backboards or other life saving devises for beach
- No fire extinguishers or ring buoys for docks
- Backfilling in the buffer zone
- Cottage # 22 outhouse in use
- Cottage # 32 installation of new retaining wall in buffer zone
- Cottage # 28 new grey water pit no approvals